

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:						
Company	Guy Davis					
OGM	Pete Hess					

Inspection Report

Permit Number:	C0150019			
Inspection Type:	COMPLETE			
Inspection Date:	Wednesday, December 08, 2010			
Start Date/Time:	12/8/2010 8:28:00 AM			
End Date/Time:	12/8/2010 10:52:00 AM			
Last Inspection:	Tuesday, August 31, 2010			

Inspector: Pete Hess.

Weather: Some clouds; 30's - 40's F. InspectionID Report Number: 2581

> Accepted by: jhelfric 12/9/2010

Permitee: ENERGY WEST MINING CO Operator: ENERGY WEST MINING CO Site: COTTONWOOD/ WILBERG

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

4,128.43	Total Permitted		
43.57	Total Disturbed		
21.29	Phase I		
21.29	Phase II		
21.29	Phase III		

Mineral Ownership

✓ Federal

State

County Fee

Other

Types of Operations

✓ Underground Surface

Loadout

Processing Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

All snow received at the site has melted off.

The site remains in temporary cessation status; there is no activity at the site.

This report, #2581, and inspection report # 2566 (records review) should be considered together as compiling the 4th Quarter 2010 Complete inspection for this site.

Inspector's Signature:

Date Wednesday, Dec



Pete Hess.

Permit Number: C0150019
Inspection Type: COMPLETE

Inspection Date: Wednesday, December 08, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓			
3.	Topsoil	~			
4.a	Hydrologic Balance: Diversions	V			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	~		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	V			
4.d	Hydrologic Balance: Water Monitoring	V		~	
4.e	Hydrologic Balance: Effluent Limitations	V		✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		~	
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage		V		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		V		
13.	Revegetation		V		
14.	Subsidence Control	Y		✓	
15.	Cessation of Operations	✓		V	
16.2	Roads: Construction, Maintenance, Surfacing	~			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	V			
20.	Air Quality Permit		✓	✓	
21.	Bonding and Insurance	✓			
22.	Other	✓		7	

Permit Number: C0150019
Inspection Type: COMPLETE

Inspection Date: Wednesday, December 08, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The Permittee has provided the additional information requested by the Division in response to the conditional approval given for the Phase II and Phase III bond release applications for the Miller Canyon portals and the Cottonwood fan portal areas. The review of that response is currently active within the Division.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The North and South ponds and the waste rock sediment pond contained either snow or frozen melt water. No compliance issues were identified. The elevation of the snow covered ice in the waste rock pond appears to indicate that the pond should be scheduled for cleanout during the summer of 2011. Mr. Davis intends to discuss this with Mr. John Christensen, P.E., who performs the impoundment inspections for the Permittee.

4.d Hydrologic Balance: Water Monitoring

Mr. Davis is, at present, entering third quarter water monitoring data for the Cottonwood / Wilberg Mine permit area into the DOGM electronic data base pipeline.

4.e Hydrologic Balance: Effluent Limitations

See inspection report # 2566, for this site dated November 24, 2010.

7. Coal Mine Waste, Refuse Piles, Impoundments

There is no activity at the waste rock site. There are no indications of spontaneous combustion, or other hazards visible or otherwise.

9. Protection of Fish, Wildlife and Related Environmental Issues

There was no wildlife observed during today's inspection.

14. Subsidence Control

Secondary extraction at this site ended prior to 2001. The Permittee continues to monitor several areas within the permit area which have yet to be determined as meeting final / maximum deformation. This data is submitted in the annual subsidence monitoring report.

15. Cessation of Operations

There has not been any change in the operational status of the site.

20. Air Quality Permit

There are no coal stockpiles at this site.

22. Other

All cyclone fence seal barricades at the mine portals remain intact.